

**Illinois Commerce Commission  
Pipeline Safety  
Exit Meeting Documentation Form**

<b>Operator:</b>	AMEREN ILLINOIS COMPANY
<b>Inspection Unit(s):</b>	Effingham
<b>Date of Meeting:</b>	08/20/2015
<b>Pipeline Safety Analyst:</b>	Donald Hankins
<b>Exit Meeting Contact:</b>	Kevin Glaspy

**Exit Statement**

**INSPECTION FINDINGS**

**Design Testing and Construction**

**Issues(s) Found:**

[NO ISSUES FOUND]

**Notice Of Amendment(s) Found:**

[NO NOAS FOUND]

**Notice Of Violation(s) Found:**

[NO NOPVS FOUND]

**PAST INSPECTION FINDINGS**

**Issue(s) Corrected:**

**2012-S002-00098** (Code Part [192.463(a)]) - Staff took cathodic readings at 1407 South 4th Street in Effingham, with the reading being -1.24. Ameren had installed three anodes to the gas main in the area to bring the readings up.

**2012-S003-00098** (Code Part [192.463(a)]) - Staff took cathodic readings at 1403 South 4th Street in Effingham, with the reading being -1.24. Ameren had installed three anodes to the gas main in the area to bring the readings up.

**2012-S004-00098** (Code Part [192.463(a)]) - Staff took cathodic readings at 1405 South 4th Street in Effingham, with the reading being -1.24. Ameren had installed three anodes to the gas main in the area to bring the readings up.

**2015-S001-00018** (Code Part [192.707(a)(2)]) - Staff determined additional line markers were needed to adequately identify the location of the distribution main between the Take Point located at 19748 US Rt. 40 and the Montrose Town Border Station.

**Notice Of Amendment(s) Corrected:**

[NO NOAS CORRECTED]

**Notice of Violations(s) Corrected:**

[NO NOPVS CORRECTED]

Pipeline Safety Analyst Signature:

Donald R Hankins

Operator Representative Signature:

Kevin Glaspy